

# Oil Field Environmental Incident Summary

**Incident:** 20150630123745      **Date/Time of Notice:** 06/30/2015 12:37

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** JACKMAN 156-100-18-19-1H

**Field Name:** EAST FORK

**Well File #:** 21197

**Date Incident:** 6/29/2015      **Time Incident:** 1200

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 100

**Sec:** 18

**Qtr:**

**Location Description:**

**Submitted By:** Corissa Zimmer

**Received By:**

**Contact Person:** Corissa Zimmer  
1700 BROADWAY STE 2300  
DENVER, CO 80290

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units
Oil	0.5	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 11/27/2015

**Clean Up Concluded:** 6/30/2015

**Risk Evaluation:**

None noted.

**Areal Extent:**

***Potential Environmental Impacts:***

None noted.

***Action Taken or Planned:***

Remedied treater pressure and will be more mindful to potential incidents like this in the future.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 7/1/2015    ***Status:*** Reviewed - Follow-up Required

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to heater/treater malfunction, impacted a pasture not on well pad, according to the report. Further follow-up needed.

---

***Date:*** 8/27/2015    ***Status:*** Inspection

***Author:*** Crowdus, Kory

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

On location 8/27/2015, at 11:43 a.m. Impacted area is to the south of well pad. No remaining impacts to vegetation or soil noted at this time. No further followup required.